



***Society of Cable  
Telecommunications  
Engineers***

---

**ENGINEERING COMMITTEE  
Interface Practices Subcommittee**

---

**AMERICAN NATIONAL STANDARD**

**ANSI/SCTE 88 2012**

**Test Methods for  
Polyethylene Jacket Longitudinal Shrinkage**

## NOTICE

The Society of Cable Telecommunications Engineers (SCTE) Recommended Practices are intended to serve the public interest by providing specifications, test methods and procedures which promote uniformity of product, interchangeability and ultimately the long term reliability of broadband facilities. These documents shall not in any way preclude any member or nonmember of SCTE from manufacturing or selling products not conforming to such documents, nor shall the existence of such practices preclude their voluntary use by those other than SCTE members, whether used domestically or internationally.

SCTE assumes no obligations or liability whatsoever to any party who may adopt the Recommended Practices. Such adopting party assumes all risks associated with adoption of these Practices, and accepts full responsibility for any damage and/or claims arising from the adoption of such Practices.

Attention is called to the possibility that implementation of this standard may require the use of subject matter covered by patent rights. By publication of this standard, no position is taken with respect to the existence or validity of any patent rights in connection therewith. SCTE shall not be responsible for identifying patents for which a license may be required or for conducting inquiries into the legal validity or scope of those patents that are brought to its attention.

Patent holders who believe that they hold patents which are essential to the implementation of this standard have been requested to provide information about those patents and any related licensing terms and conditions. Any such declarations made before or after publication of this document are available on the SCTE web site at <http://www.scte.org>.

Published by:

© Society of Cable Telecommunications Engineers, Inc. 2012

140 Philips Road

Exton, PA 19341

## TABLE OF CONTENTS

<b>Section</b>	<b>Title</b>	<b>Page</b>
1.0	SCOPE	2
2.0	EQUIPMENT	2
3.0	TEST SAMPLES	2
4.0	TEST METHODS	2
5.0	INSPECTION	3

## 1.0 SCOPE

- 1.1 The purpose of this test is to determine the amount of shrinkage of the jacketing material used on coaxial drop and distribution cables. This test procedure is applicable for use on either drop or distribution coaxial cables employing polyethylene (PE) jacketing material.

## 2.0 EQUIPMENT

- 2.1 A full draft circulation oven with a removable, thin, flat, horizontal bed of ceramic or glass beads. The oven shall be capable of meeting the following requirements for a period of four (4) hours.

100 ± 1°C (212 ± 2°F) For Low Density Materials: < 0.940 g/cm<sup>3</sup> @ 23°C (74°F)

115 ± 1°C (240 ± 2°F) For High and Medium Density Materials: > 0.940g/cm<sup>3</sup> @ 23°C (74°F)

- 2.2 Band saw or hack saw
- 2.3 A temperature indicator in the range of the specified temperature shall be used.

## 3.0 TEST SAMPLES

- 3.1 Test samples shall be 6 ±0.5 inches (150 ±10 mm) long cut from the first 100 feet of the cable reel.
- 3.2 Test samples shall be cut clean and perpendicular to the longitudinal axis of the cable. The ends of the cable samples are to be clean and square.

## 4.0 TEST METHODS

- 4.1 Preheat the full draft circulating oven with the removable bed of ceramic or glass beads in the oven for 60 minutes (1 hour) to the temperature required.
- 4.2 Place the test samples on the bed in the oven without touching one another or anything else other than the bed.

## **5.0 INSPECTION**

- 5.1 The test samples shall remain in the oven for four (4) hours at the specified temperature. Then without disturbing the test samples on the bed, remove the bed and test samples together. The bed and test samples should be placed on a flat horizontal surface that is in still air at room temperature.
- 5.2 After cooling for 60 minutes (1 hour) at room temperature, each specimen shall be measured for shrinkage of the jacket from each end of the outer conductor.
- 5.3 Record and document all measurements and observations.